



Figure 2
Site Diagram and Soil Boring
Location Map

Turkey Brook Site
20 McLennan Drive
Oakville, Connecticut

EPA Region I
Superfund Technical Assessment and
Response Team (START) III
Contract No. EP-W-05-042
TDD Number: 13-09-0009
Created by: B. Mace
Created on: 11 November 2013
Modified by:
Modified on:

Legend

- Turkey Brook
- Soil Boring Location
- Approximate Site Boundary
- Seep Location



Data Sources:
 Imagery: Esri, i-cubed, USDA, USGS, AEX,
 GeoEye, Getmapping, Aerogrid, IGN, IGP
 Topos: MicroPath
 All other data: START

